



StarSCAN® & StarMOBILE™ Release Notes — 7.02 SP2

DaimlerChrysler Corporation
Dealer Technical Operations
CIMS 486-02-60
Global Service Diagnostics
800 Chrysler Drive
Auburn Hills MI 48326-2766

StarSCAN® Application Ver.: 7.02 SP2
StarSCAN® Operating System Version: 1.55
StarMOBILE™ Application Ver.: 7.02_SP2
StarMOBILE™ Operating System Ver.: 0.40.0
Build Number: 354
Release Date: 17th November, 2006

This release of *StarSCAN*® & *StarMOBILE*™ software can only be retrieved via the Internet. An update CD will NOT be sent to your dealership for this release. To update your *StarSCAN*® and/or *StarMOBILE*™ diagnostic tool via the internet the *StarSCAN*® & *StarMOBILE*™ software version must be at version 7.01 or greater and properly configured to your dealership's network.

For assistance setting up your *StarSCAN* and/or *StarMOBILE* on your dealerships network, refer to the networking guides and tutorials located at <https://dealerconnect.chrysler.com> by navigating to DealerCONNECT > Service > Repair > *StarSCAN* and *StarMOBILE* Tools. These guides and tutorials are also available from <http://www.dcctools.com> in the 'Download Center' and 'Training Aids' sections.

StarSCAN® & StarMOBILE™ Release 7.02 SP2 Supported Vehicles:

- 2004 HB
- 2005 HB, LX, ND, WK, WH
- 2006 DR, HB, KJ, LX, LE, ND, NM, PT, WK, WH, XK, XH
- 2006 LX SRT-8, WK SRT-8, DR SRT-10, PT 1.6L
- 2007 CS, DR, HB, HG, JK, JS, KA, KJ, LX, LE, MK, ND, NM, PM, PT, WK, XK, ZH

Detailed Vehicle Support Information:

- 2006 and 2007 DR TIPM —Modified the VIN checking portion of the Restore Vehicle Configuration routine
- 2007 JS TIPM —Added JPY sales code for the DDM and PDM which is used during the Restore Vehicle Configuration routine
- 2007 WH FCM – Fixed the brake lighting issue causing turn signals to come on with brake lights after running the Restore Vehicle Configuration routine
- 2007 LX 2.7L FCM/CGW – Program Tire Size routine fixed to write pinion factor to TCM.
- 2006 KJ 2.8L Diesel WCM – PCM Replaced routine fixed to write VIN to PCM upon PCM replacement.
- 2007 ZH initial diagnostic support
- 2007 NGC4 62TE – Added LC and DC CVI's

Core Software Information:

New Features:

- 2007 KJ BCM automated model year write.
- 2007 ZH final core software support.
- 2007 Flash Support for three new HVAC ECUs.