



## **StarSCAN® & StarMOBILE™ Latest News — 6.05 SP1**

DaimlerChrysler Corporation  
Dealer Technical Operations  
CIMS 486-02-60  
Global Service Diagnostics  
800 Chrysler Drive  
Auburn Hills MI 48326-2766

StarSCAN® Application Ver.: 6.05 SP1  
StarSCAN® Operating System Version: 1.51  
StarMOBILE™ Application Ver.: 6.05 SP1  
StarMOBILE™ Operating System Ver.: 0.29.7  
Release Date: 17<sup>th</sup> January, 2006

This release of *StarSCAN*® & *StarMOBILE*™ software can only be retrieved via the Internet. An update CD **will not** be sent to your dealership for this release. To update your *StarSCAN*® and/or *StarMOBILE*™ diagnostic tool via the internet the *StarSCAN*® & *StarMOBILE*™ software version must be at version **6.05** and properly configured to your dealership's network.

For assistance setting up your StarSCAN and/or StarMOBILE on your dealerships network, refer to the networking guides and tutorials located at <https://dealerconnect.chrysler.com> by navigating to DealerCONNECT > Service > Repair > StarSCAN and StarMOBILE Tools. These guides and tutorials are also available from <http://www.dcctools.com> in the 'Download Center' and 'Training Aids' sections.

### **StarSCAN® & StarMOBILE™ Release 6.05 SP1 Supported Vehicles:**

- 2004 HB
- 2005 HB, LX, ND, WK, WH
- 2006 HB, LX, ND, WK, WH, XK, XH, DR, KJ, PT, LE, NM
- 2006 LX SRT-8, WK SRT-8, DR SRT-10, PT 1.6L
- 2007 PM

### **Detailed Vehicle Support Information:**

- 2006 LX FCM – Program Tire Size routine updated with new tire sizes
- 2006 LX FCM – Restore Vehicle Configuration Routine updated with new tire sizes and AHBM ability
- 2006 HB ABS - Initialize ECU routine fixed. Was not properly initializing ABS Only vehicles
- 2006 KJ BCM - Added support for "other" tire size entry
- 2006 ALL NGC3 – "Reset ECU" feature added.
- 2007 PM CCN - The following Misc Functions have been removed from PM CCN: Language Preferences, Unlock Driver Door On 1st Press, and Measurement Units
- 2007 PM WCM - WCM Replaced for diesel and gas application fixed.
- 2007 PM GPEC PCM Flash support



## StarSCAN® & StarMOBILE™ Latest News — 6.05 SP1

### **Items Not Yet Supported:**

- GPEC OBDII Monitors
- 2007 PM TIPM – Restore Vehicle Configuration Routine
- 2007 PM Bosch EDC16-U31 ECM - **Variant Coding** miscellaneous function

### **Core Software Information:**

**Note** – *This release does not contain a new release of the core software or operating system.*

### **General Information & Tips:**

- ALL - Clear All Stored DTCs - When the user selects the confirmation box to clear all stored DTCs, the text visible outside the dialog box remains on the screen until user exits the DTC menu and re-enters. The lingering text gives the appearance that DTCs have not been cleared. This will be corrected in a future release.