



StarSCAN® & StarMOBILE™ Latest News — 6.05 SP2

DaimlerChrysler Corporation
Dealer Technical Operations
CIMS 486-02-60
Global Service Diagnostics
800 Chrysler Drive
Auburn Hills MI 48326-2766

StarSCAN® Application Ver.: 6.05 SP2
StarSCAN® Operating System Version: 1.51
StarMOBILE™ Application Ver.: 6.05 SP2
StarMOBILE™ Operating System Ver.: 0.29.7
Build Number: 7
Release Date: 30th January, 2006

This release of *StarSCAN*® & *StarMOBILE*™ software can only be retrieved via the Internet. An update CD will **NOT** be sent to your dealership for this release. To update your *StarSCAN*® and/or *StarMOBILE*™ diagnostic tool via the internet the *StarSCAN*® & *StarMOBILE*™ software version must be at version **6.05** or greater and properly configured to your dealership's network.

For assistance setting up your StarSCAN and/or StarMOBILE on your dealerships network, refer to the networking guides and tutorials located at <https://dealerconnect.chrysler.com> by navigating to DealerCONNECT > Service > Repair > StarSCAN and StarMOBILE Tools. These guides and tutorials are also available from <http://www.dcctools.com> in the 'Download Center' and 'Training Aids' sections.

***StarSCAN*® & *StarMOBILE*™ Release 6.05 SP2 Supported Vehicles:**

- 2004 HB
- 2005 HB, LX, ND, WK, WH
- 2006 HB, LX, ND, WK, WH, XK, XH, DR, KJ, PT, LE, NM
- 2006 LX SRT-8, WK SRT-8, DR SRT-10, PT 1.6L
- 2007 PM

Detailed Vehicle Support Information:

- 2006 KJ 2.8L TCM Flash



StarSCAN® & StarMOBILE™ Latest News — 6.05 SP2

Items Not Yet Supported:

- GPEC OBDII Monitors
- 2007 PM TIPM – Restore Vehicle Configuration Routine
- 2007 PM Bosch EDC16-U31 ECM - **Variant Coding** miscellaneous function

Core Software Information:

Note – This release does not contain a new release of the core software or operating system.

General Information & Tips:

- ALL - Clear All Stored DTCs - When the user selects the confirmation box to clear all stored DTCs, the text visible outside the dialog box remains on the screen until user exits the DTC menu and re-enters. The lingering text gives the appearance that DTCs have not been cleared. This will be corrected in a future release.