



StarSCAN® & StarMOBILE® Release Notes — 7.04 SP1

DaimlerChrysler Corporation
 Dealer Technical Operations
 CIMS 486-02-60
 Global Service Diagnostics
 800 Chrysler Drive
 Auburn Hills MI 48326-2766

StarSCAN® Application Ver.: 7.04 SP1
 StarSCAN® Operating System Version: 1.65
 StarMOBILE® Application Version: 7.04 SP1
 StarMOBILE® Operating System Version: 0.45.1
 Build Number: 20
 Release Date: 5/1/2007

This release of StarSCAN® & StarMOBILE® software can only be retrieved via the Internet. An update CD will NOT be sent to your dealership for this release. To update your StarSCAN® and/or StarMOBILE® diagnostic tool via the internet, the StarSCAN® & StarMOBILE® software version must be at version 7.03 or greater and properly configured to your dealership's network.

For assistance setting up your StarSCAN® and/or StarMOBILE® on your dealerships network, refer to the networking guides and tutorials located at <https://dealerconnect.chrysler.com> by navigating to DealerCONNECT > Service > Repair > StarSCAN and StarMOBILE Tools. These guides and tutorials are also available from <http://www.dcctools.com> in the 'Download Center' and 'Training Aids' sections.

StarSCAN® & StarMOBILE® Supported Vehicles:

Supported Vehicle Applications:

Model Year	Vehicles
2004	HB
2005	HB, LX, ND, WK, WH
2006	DR, HB, KJ, LX, LE, ND, PT, WK, WH, XK, XH
2007	CS, DR, HB, HG, JK, JS, KA, KJ, LX, LE, MK, ND, PM, PT, VB, WK, WH, XK, XH, ZH
2008	JS

Detailed Vehicle Support Information:

Fixes/Corrections:

MY(s) / Vehicle(s)	ECU	Change Description	Tracking #
2007 JK	TIPM	Updated the Restore Vehicle Configuration routine to always turn the CCN configuration bit on	Production-18
2005 WK, LX, ND, HB	PCM – NGC3	All Miscellaneous Functions & System Tests Added	Field-28
2006 DR SRT-10	WCM	Corrected "Program Ignition Keys" routine to allow programming of ignition keys	Production-25